


Lasers Technical stop 25 April

Laser power measurement campaign to understand lasers power level:

Photonics calibration curve :



Working point: 55 A

Lasers Technical stop 25 April

Laser power measurement with the current setting for ECAL sequence :

Ti:S1 : 20A, 50% of the internal attenuator.
DP2-447: 55A, no attenuation
Green: fixed setting (saclay...)

	Power from laser output (1)	Power before the 1x100 switch + 10m fibre (2) , no attenuation	Same as (2) but with remote attenuation 50%	Same as (2) but with remote attenuation 30%
Ti:S 1	40 mW	2 mW	1 mW	0.56 mW
DP2-447	87.6 mW	2 mW	1 mW	0.60 mW
Green	-	0.450 mW	Too low for power meter	-

Before the 1x100 :

IL(TiS) = 13 dB

→ a bit too high because of no 1x100 switch included

IL(DP2-447) = 16.4 dB

→ too high, should be consistent with TiS laser.

Remote linear attenuator: OK, power is consistent with the % of attenuation

Lasers Technical stop 26 April

	Setup to check TiS laser path	IL (dB)
①	<p style="text-align: center;">Test fibre: 10m</p> <p style="text-align: center;">40mW 32mW</p>	1 dB
②	<p style="text-align: center;">Main fibre 20m Test fibre</p> <p style="text-align: center;">40mW 22,7 mW</p>	2.4 dB
③	<p style="text-align: center;">Main fibre Test fibre</p> <p style="text-align: center;">40mW 12.5 mW</p> <p style="text-align: center;">1X5 1m fibre *</p>	5 dB + 1x5 switch = 2 dB + FC connector = 0.5db = 2.5 dB → OK
④	<p style="text-align: center;">Test fibre</p> <p style="text-align: center;">40mW 6.3 mW</p> <p style="text-align: center;">1X5 Att. box</p>	8 dB + Att. Box = 2.5dB + FC connector = 0.5db = 3dB → OK
⑤	<p style="text-align: center;">Test fibre</p> <p style="text-align: center;">40mW 2 mW</p> <p style="text-align: center;">1X5 Att. box 1x 100</p>	13dB IL(dB) for TiS 1 : OK


* 1m fibre: 1m fibre + FC connector is there to avoid disconnection from optical switch directly.

Lasers Technical stop 26 April

Setup to check TiS laser path


IL (dB)

Check the 1x100 switch only keeping the 1m fibre:



5.6 dB

Check the 1x100 switch only , with the main tiS fibre directly on the switch:



4.55 dB

Compare to 2) : $\Delta=4.55-2.5= 2$ dB
just for the switch. OK here


Photonics:

No improvement the 26 April , same power: cleanning-polishing fibre from the attenuation box and 1x100 switch didn't help.

Lasers Technical stop 27 April

Setup to check DP2 laser path

IL (dB)



Lasers Technical stop 27 April

Results :

- 1) clean and polish some fibre in the chain: some of them were bad.
- 2) TiS attenuation was OK: main fibre and full chain OK
- 3) DP2 attenuation was BAD: main fibre dirty.



DP2-447 amplitude no more visible on the light Checker (too high)

- Decrease the internal attenuation from 100 to 40%;
- Wait before decreasing the current at the same time because now useless to have high current;
- Change the external attenuation